

Blanik L23 N363BA Checklist

Speeds (kts)

Vs	32
Vs1 (w airbrakes out)	36
Vms	37 (160 fpm)
Vg (Max L/D)	49 (28:1) solo 43
Va	81
Vaerotow	81
Vautotow	65
Vne	124
Vappr (book)	49-51
w air brakes full	51-60
Vappr (1.5 Vs1)	54
mgw	1124#
empty wt	712#
Min solo wt	154
max useful load	412

Before Takeoff - **AABBCCDE**

A	Altimeter - set
A	Airbrakes closed/locked
B	Ballast - if required
B	Belts - secure & adjust
C	Controls - free/correct, trim
C	Cable - check & attach
C	Canopy - closed & latched
D	Direction of Wind
E	Emergencies - review

Before Landing - **W USTALL**

W	Wind - assess
U	Undercarriage down
S	Speed - 1/d + 1/2 wind + gust
T	Trim - set
A	Airbrakes - check/use
L	Look - traffic,/landing/wind
L	Land - adjust for conditions

After Landing:

Radio off, Airbrakes open, Canopy closed, Windows closed,
Fill out Pilot Sortie Log

Blanik L23 N363BA Checklist

Speeds (kts)

Vs	32
Vs1 (w airbrakes out)	36
Vms	37 (160 fpm)
Vg (Max L/D)	49 (28:1) solo 43
Va	81
Vaerotow	81
Vautotow	65
Vne	124
Vappr (book)	49-51
w air brakes full	51-60
Vappr (1.5 Vs1)	54
mgw	1124#
empty wt	712#
Min solo wt	154
max useful load	412

Before Takeoff - **AABBCCDE**

A	Altimeter - set
A	Airbrakes closed/locked
B	Ballast - if required
B	Belts - secure & adjust
C	Controls - free/correct, trim
C	Cable - check & attach
C	Canopy - closed & latched
D	Direction of Wind
E	Emergencies - review

Before Landing - **W USTALL**

W	Wind - assess
U	Undercarriage down
S	Speed - 1/d + 1/2 wind + gust
T	Trim - set
A	Airbrakes - check/use
L	Look - traffic,/landing/wind
L	Land - adjust for conditions

After Landing:

Radio off, Airbrakes open, Canopy closed, Windows closed,
Fill out Pilot Sortie Log